

Installation:

1. Uninstall older program version.
2. Restart PC.
3. Install program from "Setup" folder.
4. Restart PC.
5. From folder "Crack" copy file "Mach1Lic.dat" to program folder. Default (C:\Mach3\).
6. From folder "Crack" copy file "Mach3.exe" to program folder. Default (C:\Mach3\).
7. Restart PC.
8. Run G-Code file with more than 500 lines.

by iran-cnc3d.blogfa.com    iran.cnc@yahoo.com